



# GEMPLUX TEST REPORT

## Super Stainless

### Abstract

Test carried out on Super Stainless – Stainless Steel Protector to evaluate if corrosion once removed by the product would come back

**Mayelyn Blackerby**  
Quality Control Engineer  
[mayelyn@gemlux.com](mailto:mayelyn@gemlux.com)  
[www.gemlux.com](http://www.gemlux.com)

[800.874.4506](tel:800.874.4506) Tel  
[904.269.5905](tel:904.269.5905) Fax  
[904.444.1752](tel:904.444.1752) Cell  
[140 Industrial Loop](http://www.gemlux.com)  
[Orange Park, FL 32073](http://www.gemlux.com)

**Viewing Salt Spray Sample: (# 832)**

Hinge 3 x 2 Cutting  
 Item #: Edge  
 Source: G8234  
 Date Created: 06/03/16  
 Created By: Mayelyn Alvarez  
 Start Test  
 Time: 6/3/16 8:00  
 Test Hours: 400  
 Finish Result: **Pass**

**Sample Comments:**

Date	Hours	User	Comment
06/04/16	24	Mayelyn Alvarez	No corrosion present
06/07/16	100	Mayelyn Alvarez	No corrosion present
06/10/16	200	Mayelyn Alvarez	No corrosion present
06/13/16	300	Mayelyn Alvarez	No corrosion present
06/16/16	400	Mayelyn Alvarez	No corrosion present
			<b>SAMPLE WAS CLOSED WITH RESULT: Pass</b>

**Viewing Salt Spray Sample: (# 833)**

Rod Holder  
 Item #: Rod Holder  
 Source: G8230  
 Date Created: 06/03/16  
 Created By: Mayelyn Alvarez  
 Start Test  
 Time: 6/3/16 8:00  
 Test Hours: 400  
 Finish Result: **Pass**

**Sample Comments:**

Date	Hours	User	Comment
06/04/16	24	Mayelyn Alvarez	No corrosion present
06/07/16	100	Mayelyn Alvarez	No corrosion present
06/10/16	200	Mayelyn Alvarez	No corrosion present
06/13/16	300	Mayelyn Alvarez	No corrosion present
06/16/16	400	Mayelyn Alvarez	No corrosion present
			<b>SAMPLE WAS CLOSED WITH RESULT: Pass</b>

**Viewing Salt Spray Sample: (# 834)**

Item #: Thru Hull  
 Source: G8231  
 Date Created: 06/03/16  
 Created By: Mayelyn Alvarez  
 Start Test  
 Time: 6/3/16 8:00  
 Test Hours: 400  
 Finish Result: Pass

**Sample Comments:**

Date	Hours	User	Comment
06/04/16	24	Mayelyn Alvarez	No corrosion present
06/07/16	100	Mayelyn Alvarez	No corrosion present
06/10/16	200	Mayelyn Alvarez	No corrosion present
06/13/16	300	Mayelyn Alvarez	No corrosion present
06/16/16	400	Mayelyn Alvarez	No corrosion present
			<b>SAMPLE WAS CLOSED WITH RESULT: Pass</b>

**Viewing Salt Spray Sample: (# 835)**

Item #: Hinge Cast  
 Source: G8199  
 Date Created: 06/03/16  
 Created By: Mayelyn Alvarez  
 Start Test  
 Time: 6/3/16 8:00  
 Test Hours: 400  
 Finish Result: Pass

**Sample Comments:**

Date	Hours	User	Comment
06/04/16	24	Mayelyn Alvarez	No corrosion present
06/07/16	100	Mayelyn Alvarez	No corrosion present
06/10/16	200	Mayelyn Alvarez	No corrosion present
06/13/16	300	Mayelyn Alvarez	No corrosion present
06/16/16	400	Mayelyn Alvarez	No corrosion present
			<b>SAMPLE WAS CLOSED WITH RESULT: Pass</b>

**Viewing Salt Spray Sample: (# 836)**

Item #: Steering Wheel  
 Source: G8231  
 Date Created: 06/03/16  
 Created By: Mayelyn Alvarez  
 Start Test  
 Time: 6/3/16 8:00  
 Test Hours: 400  
 Finish Result: **Pass**

**Sample Comments:**

Date	Hours	User	Comment
06/04/16	24	Mayelyn Alvarez	No corrosion present
06/07/16	100	Mayelyn Alvarez	No corrosion present
06/10/16	200	Mayelyn Alvarez	No corrosion present
06/13/16	300	Mayelyn Alvarez	No corrosion present
06/16/16	400	Mayelyn Alvarez	No corrosion present
			<b>SAMPLE WAS CLOSED WITH RESULT: Pass</b>

**Before and After Pictures:**





















